

사 진 자 료



<풍수해로 붕괴된 담장보수 전·후(국가민속문화재 제122호 안동 하회마을)>



<훼손된 고택 벽체보수 전·후(시도유형문화재 제207호 영덕 경수당종택)>



<기와고르기(보물 제414호
안동 하회 충효당)>



<담장보수(전라남도민속문화재 제5호
담양 고재선 가옥)>



<문화재 돌봄교육(한식미장·목조문화재 모니터링)>

